PGDP KEVIL DMC MATERIAL TRANSFER FORM



To ensure inclusion in the correct project file, this form MUST be attached to materials being transferred to the DMC. Please fill in all blanks in top of form. Use n/a if not applicable.

5 M 00007, Data assessmen	Phy FY99 Document Date:
Document Number.	Page Count:.
19-45-3	
Author/Organization: Jana White	Facility/WAG/SWMU:
Project Program/Title:	Document Prep. Checklist
	Attached: ☐ Yes ☐ No
	Clearance Form: (when required) Attached: Yes No
Keywords/Identifiers/ "Buzz Words"	
1 2	3
4 5	6
* QA Record: Yes No	
Submitted by: Date:	Phone:
*Quality Assurance (QA) Record is a completed document that furnishes evidence of the quality of items and/or activities affecting quality. PORTION BELOW TO BE COMPLETED BY DMC STAFF	
Comments:	
Publication Data:	Related Documents:
Status (RC, ARF, Library): REC, 6, V	Vital Record: ☐ Yes ☐ No
FG RR PJ/RS 60017 Item #	0078
Indexed by: LR GOOT	C/S Date: 2/21/00

CP-20443 (5 5-16-95)



RECORD COPY

Data Assessment Packages for:
GW99-07
SS99-03
404L99-02
KP99-07 THRU KP99-12
SL99-04 THRU SL99-06
UG99-03 & UG99-04
KG99-03 & KG99-04
GWRES99-07 THRU GWRES99-12
SG99-03 & SG99-04
ERI99-BP-SWMU45
US99-03 & US99-04
UL99-02 THRU UL99-04
PLRES99-01 THRU PLRES99-07
CARB99-05 & CARB99-06
404 <i>G</i> 99-01 & 404 <i>G</i> 99-02